Upgrade Information of MPE720 Version 7.28

1. Added and Improved Functions

1.1 Ver.7.28Upgrade Information

Items added and features improved from MPE720 version 7.27 to version 7.28 are as follows.

No.	Feature	Classification
1	The MP3300 (CPU-301(32 axes)) controller was supported.	Add function
2	The Sigma-7W (SGD7W-****20*) SERVOPACK of 2-axis driving model was added.	Add function
3	MPHLS-01 module (HLS communication module) was added in the option modules of MP3000 series. Add function	
4	The maintenance monitor function was added.	Add function
5	The maximum communication size setting function was added to the communication platform. Functional enhancer	
6	The updating timing of comments has been improved in the Replace in project function. Improvement	
7	"Address search" in the search in project has been improved. Improvement	
8	The updating timing of the Setting Parameter and the Monitor Parameter has been improved. Improvement	
9	The current value display of the Ladder program has been improved. Improvement	
10	The operation of the "Write the parameter into the SERVOPACK" optional feature of Transfer function has been improved. Improvement	
11	"Save to Flash" operation has been improved.	Improvement
12	Enable or Disable switching behavior of CP Ladder was improved.	Malfunction correction

(*): When MPE720 Ver.7 before MPE720 Ver.7.11 is already installed in Windows Vista and Windows 7, it may not operate for the newest information of the servo model addition by the axial setup wizard function (the newest information added into the database) updated by after MPE720 Ver.7.13.

Please refer to the following page for operating procedures.

[About the restriction matter when using MPE720 Ver.7 in Windows Vista and Windows 7]

When MPE720 Ver.7 is used in Windows Vista and Windows 7, the following phenomena might be generated.

<Phenomena>

When MPE720 Ver.7 before MPE720 Ver.7.11 is already installed in Windows Vista and Windows 7, it may not operate for the newest information of the servo model addition by the axial setup wizard function (the newest information added into the database) updated by after MPE720 Ver.7.13.

<Measures>

Using a batch file, the following folder is deleted. (*1)

C:\fores\for

Procedure

1. The batch file enclosed by MPE720 Ver.7 installer is copied to a desktop.

[Download Version]

MPE720Ver7 xxx(*4)\piTools\piCleanUp\piMPE720Ver7 x86.bat (32bitOS)

MPE720Ver7 xxx(*4)\pmuTools\pmuCleanUp\pmPE720Ver7 x64.bat (64bitOS)

[DVD Media Version]


D(*5):\text{\text{Y}Tools}\text{\text{CleanUp}\text{\text{MPE}720Ver7} x86.bat (32bitOS)}

D(*5):\text{\text{YTools}\text{\text{CleanUp}\text{\text{MPE}720Ver7}_x64.bat} (64\text{bitOS})


2. The copied batch file is performed.

MPE720Ver7_x86.bat (32bitOS)


MPE720Ver7 x64.bat (64bitOS)



3. "y" is inputted on a command prompt and the Enter button is pushed.



4. The Enter button is pushed on a command prompt after deletion.



- (*1): When multi-user is using one set of PC, please operate it by each user.
- (*2): The user account name that logs in enters.
- (*3): The path changes by OS.

32bitOS: Program Files

64bitOS: Program Files (x86)

- (*4): The path changes by version.
- (*5): The path changes by DVD drive.
- (*6): When an installation path is changed at the time of MPE720 Ver.7 installation, please delete the "MPE720 Ver7" folder which a folder subordinate has below manually according to the installed path.

C:\Users\UserName(*2)\UserData\Local\User\User\userbare

[About compile of the parallel circuit]


In the Ladder program of MPE720 Ver7 before MPE720 Ver7.23, when the parallel circuit is used, the following phenomena may occur.

<Phenomena>

When the circuit containing the following pattern was created, there was a phenomenon of operating without receiving the condition that the circuit below the OR circuit of 1st class must operate essentially in response to the conditional instruction before the OR circuit of 1st class.

<Measures>

When a phenomenon occurs, please carry out re-compile about the Ladder program in MPE720 Ver7 after MPE720 Ver7.24. Or please carry out again "Compile All Programs" of "Compile" menu.



The OR circuit of 1st class: The OR circuit branched from the bus-bar of langue.

The OR circuit of 2nd class: The OR circuit branched out of the OR circuit of 1st class.

The OR circuit of 3rd class: The OR circuit branched out of the OR circuit of 2nd class.

□(Conditional instruction): NO Contact, NC Contact, Coil, instruction(==, !=, >, <), power line (-----) etc.

☆(Output instruction): Coil, Block instruction(Expression, STORE, COPYW) etc


XHowever, when all ☆ is coil commands, a phenomenon does not occur.


△(Output instruction): Coil, Block instruction(Expression, STORE, COPYW)etc

<Pattern>

Symbol	Instruction
][NO Contact
STORE	STORE instruction
()	Coil

<NG Pattern>





1.2 Past Upgrade Information

No.	Upgrade Information	Remarks	
1	MPE720 version 7.11 upgrade information	version 7.10→version 7.11	
2	MPE720 version 7.13 upgrade information	version 7.11→version 7.13	
3	MPE720 version 7.14 upgrade information	version 7.13→version 7.14	
4	MPE720 version 7.20 upgrade information	version 7.14→version 7.20	
5	MPE720 version 7.21 upgrade information	version 7.20→version 7.21	
6	MPE720 version 7.23 upgrade information	version 7.21→version 7.23	
7	MPE720 version 7.24 upgrade information	version 7.23→version 7.24	
8	MPE720 version 7.26 upgrade information	version 7.24→version 7.26	
9	MPE720 version 7.27 upgrade information	version 7.26→version 7.27	

2. Description

No. 1 The MP3300 (CPU-301(32 axes)) controller was supported.

MP3300 (CPU-301(32 axes)) controller was supported.

1. For CPU-301(32 axes) controller

CPU-301(32 axes) controller was added.

The SVC module built in CPU can connect up to 32 axes.

2. The back ground flash preservation function

The function to save the flash on the back ground was supported as a new function of MP3300.

The other engineering operations cannot be done up to now until the flash preservation is completed. And the other engineering operations are possible while saving the flash.

The status of the flash preservation can be monitored by confirming the status bar.

As for the flash preservation operation, it is the same.

3. The FTP server and FTP client function

The logging data and the register data stored in with built-in CPU RAM or USB memory can be downloaded from remoteness to the device by the file transfer feature (FTP server function).

4. The start measuring high-speed scan processing time mode

The start measuring high-speed scan processing time mode was supported. The function was able to be selected "From 1st scan" and "From 2nd scan".

The best function for the application where initialization etc. is executed to the first scan when the power supply is turned on, or the high-speed scan is postponed only to the first scan, where high-speed time over etc. is generated.

Controller	Support Version
MP3000 Series	MP3300 (CPU-301(32axes)) Ver1.12 or later
MP2000 Series	There is no correspondence.

No. 2 The Sigma-7W (SGD7W-****20*) SERVOPACK of 2-axis driving model was added.

The Sigma-7 series SERVOPACK (2-axis driving model of MECHATROLINK-III communications reference, Sigma-7W (SGD7W-****20*)) was supported.

1. Module Configuration

In the Module Configuration, it changed so that the Sigma-7W series could be assigned.

2. Fixed, Setting, Monitor Parameter

The screen for carrying out a detailed setup of Fixed Parameters, Setting Parameters and Monitor Parameters of the Sigma-7W series was added.

3. Servo Parameter, Servo Monitor

The screen for carrying out a detailed setup of Servo Parameter and Servo Monitor of the Sigma-7W series was added.

Madula	Module Function Module/Slave		Circuit No/AxisAddress		Matina Danistan
		Status	Start	supied circu	Motion Register
01 [CPU-301(32axes)]:					
	01 CPU				
	02 218IFD		器 Circuit No1	1	
	03 🖃 SVC32		□ Circuit No1	2	8000 - 8FFF[H]
			04[H]		
	01 a Control Axis(Rotary)		(00[H])		8000 - 807F[H]
	02 🤖 Control Axis(Rotary)		 (01[H])		8080 - 80FF[H]
= 00 (a) CPU301(32)[]	00 טואטבו אאבט				
의 (0) ⊕ CPU301(32)[] MB U- 38	04 UNDEFINED				
<u> </u>	05 UNDEFINED				
8	06 UNDEFINED				
	07 UNDEFINED				
	08 UNDEFINED				
	04 ± SVR32		□ Circuit No3	2	9000 - 9FFF[H]
	05 M-EXECUTOR				
	06 UNDEFINED				
	07 UNDEFINED				

[Support Version]

Controller


Controller		Support Version
MP3200	CPU-201, CPU-201(SUB), Ver1.12 or lat	
	CPU-202, CPU-202(SUB)	
MP3300	0 CPU-301(16axes) Ver1.10 or late	
CPU-301(32axes) Ver1.12 or lat		Ver1.12 or later
MP2000 Series		Ver2.88 or later

Option Module

Module	Support Version
SVC-01	Ver1.12 or later

No. 3 MPHLS-01 module (HLS communication module) was added in the option modules of MP3000 series.

MPHLS-01 module (HLS communication module: product by M-System Co, Ltd) was added to the option module with which MP3000 series can be assigned.



[Support Version]

Controller

Controller	Support Version
MP3000 Series	Ver1.12 or later
MP2000 Series	Ver2.84 or later

Option Module


Module	Support Version
MPHLS-01	Ver1.00 or later

No. 4 The maintenance monitor function was added.

The maintenance monitor function was added as a new function of MP3000 series.

In the maintenance monitor function, it can monitor by assigning to the system register of MP3000 series controller by a user's operation about the following information which the SERVOPACK has.

Category	Item
	Power consumption per unit time
Power consumption monitor	Accumulated power consumption
	Accumulated power consumption (after the decimal point)
Installation environment monitor	Servopack installation environment
Installation environment monitor	Motor installation environment
	Total operation time
	Built in fan lifetime
Lifetime monitor	Built in capacitor lifetime
	Rush current prevention circuit lifetime
	Dynamic brake circuit lifetime




Controller	Support Version
MP3000 Series	Ver1.12 or later
MP2000 Series	There is no correspondence.

No. 5 The maximum communication size setting function was added to the communication platform.

The maximum communication size setting function was added to the following communication port of the communication platform.


- USB communication
- Serial communication



Controller Support Version	
MP3000 Series	It is not dependent on the version.
MP2000 Series	It is not dependent on the version.

No. 6 The updating timing of comments has been improved in the Replace in project function.


There was a phenomenon that the register comments in CP Ladder are not updated, when register comments move optional function was used in the replace in project function. So, this has been improved.



Controller	Support Version
MP3000 Series	It is not dependent on the version.
MP2000 Series	It is not dependent on the version.

No. 7 "Address search" in the search in project has been improved.

In the search in project, since there was a phenomenon in which the register used for the Expression command was not searched when address search was carried out. So, this has been improved.



Controller	Support Version
MP3000 Series	It is not dependent on the version.
MP2000 Series	It is not dependent on the version.

No. 8 The updating timing of the Setting Parameter and the Monitor Parameter has been improved.

Since there was a phenomenon in which a display is updated with the unit of a starting value about the following parameter (unit) when the motion register was changed in the Setting Parameter and the Monitor parameter of MC-Configurator. So, this has been improved.


- -Speed unit selection
- -Acceleration/ Deceleration unit selection
- -Torque unit selection

1 2 *	Address	Axis0101 Circuit#01 Axis#01 SGD7S-****20* [Initial value]		Axis0101 Circuit#01 Axis#01 SGD7S-****20*		Axis0102 Circuit#01 Axis#02 SGDV-****21* (AC Inp···	
		Select All	Reflectio	Update		Update	
⊕ 0 : Run command setting	OW8000		0000[H]		0000[H] 🛄		0000[H]
1 : Mode setting 1	OW8001		0000[H]		0000[H]		0000(H)
⊕ 2: Mode setting 2	OW8002		0000[H]		0000[H]		0000(H)
⊕ 3 : Function setting 1	OW8003		0011[H]		0000[H]		1011[H]
4 : Function setting 2	OW8004		0033[H]		0033[H]		0033[H]
⊕ 5 : Function setting 3	OW8005		0000[H]		0000[H]		0000[H]
⊕ 6 : M-III Vendor Specific Servo Comma···	OW8006		0000[H]		0000[H]		0000[H]
8 : Motion command	OW8008		0 : No Command	() : No Command	0	: No Command
⊕ 9 : Motion command control flag	OW8009		0000[H]		0000[H]		0000[H]
10 : Motion subcommand	A008WO		0 : No Command	() : No Command	0	: No Command
12 : Torque/Thrust reference setting	OL800C		0[0.01%]		0[0.01%]		0[0.0001%]
14: Speed limit setting at the torque/th···	OW800E		15000[0.01%]		15000[0.01%]		15000[0.01%]
16 : Speed reference setting	OL8010	3000	[1000pulse/min]		3000[pulse/s]	3000[1000pulse/min]
18 : Speed limit value	OW8012		0[0.01%]		0[0.01%]		0[0.01%]
20: Positive side limiting torque/thrust…	OL8014		30000[0.01%]		30000[0.01%]		30000[0.0001%]
22 : Secondly Speed Compensation	OL8016	0	[1000pulse/min]		0[pulse/s]	0[1000pulse/min]
24 : Override	OW8018		10000[0.01%]		10000[0.01%]		100000[0.01%]
28 : Position reference setting	OL801C		0[pulse]		0[pulse]		0[pulse]
30 : Width of positioning completion	OL801E		100[pulse]		100[pulse]		100[pulse]
32 : NEAR signal output width	OL8020		0[pulse]		0[pulse]		0[pulse]
34 : Error count alarm detection	OL8022	<u> </u>	47483647[pulse]	214	17483647[pulse]	214	7483647[pulse]
38 : Positioning completion check time	OW8026		0[ms]		0[ms]		0[ms]
40 : Phase correction setting	OL8028		0[pulse]		0[pulse]		0[pulse]
42 : Latch zone lower limit setting	OL802A	-21	47483648[pulse]	-214	17483648[pulse]	-214	7483648[pulse]
44 : Latch zone upper limit setting	OT-802C	21	47483647[pulse]	214	17483647[pulse]	214	7483647[pulse]

Controller	Support Version
MP3000 Series	It is not dependent on the version.
MP2000 Series	It is not dependent on the version.

No. 9 The current value display of the Ladder program has been improved.

In the Ladder program, since "0" might be displayed on the index of the arrangement register currently used for the command in which conditions are not satisfied. So, this has been improved.



[Support Version]

Controller	Support Version
MP3000 Series	It is not dependent on the version.
MP2000 Series	Unsupported.

No. 10 The operation of the "Write the parameter into the SERVOPACK" optional feature of Transfer

function has been improved.

The following improvement was carried out about the operation of the "Write the parameter into the SERVOPACK" optional feature of Transfer function.

[Phenomenon]

- 1. When the SERVOPACK which cannot do the writing of parameters existed in the SERVOPACK assigned to SVB or SVC (Ex the SERVOPACK does not exist etc.), it had interrupted the writing of parameters to the SERVOPACK after its station.
- 2. When this phenomenon occurred, the message was displayed "Writing was completed normally" on the Transfer log.

[Improvement operation]

- 1. Even when the servo pack which cannot be written in exists, it has improved the operation continues the writing to the SERVOPACK after the station.
- 2. The SERVOPACK which was not able to be written in has improved so that an error log may be displayed on the Transfer log.

Controller	Support Version
MP3000 Series	It is not dependent on the version.
MP2000 Series	It is not dependent on the version.

No. 11 "Save to Flash" operation has been improved.

Since there was a phenomenon that the status of "Save to Flash" operation could not be checked when the project file was opened in the off-line, and the check was attached to "Save to flash after transferring to the controller" and it carried out "Write into controller". So, this has been improved.

* It is that a phenomenon occurs in CPU-301 (16axes).

[Support Version]

Controller	Support Version
MP3000 Series	It is not dependent on the version.
MP2000 Series	It is not dependent on the version.

No. 12 Enable or Disable switching behavior of CP Ladder was improved.

In the program tree of Ladder window, when the enable and disable of CP Ladder were changed, there was fault that the error message was displayed and the change cannot perform.

Controller	Support Version
MP3000 Series	It is not dependent on the version.
MP2000 Series	It is not dependent on the version.